

testo 545 Luminous intensity measuring instrument

Instruction manual

en



Contents

Contents
nitial operation
First measurement
nstrument description
-Keypad/Connection assignment
-Display
Overview of controls
Current measurement
Switching on
Saving, Printing
Measurement functions
Freezing readings11
Maximum readings
Minimum readings
Multi-point mean calculation
Timed mean calculation
ocation selection
Measuring range switchover function
Memory settings
Overview
Manual / Automatic saving16
Reading out or printing memory17
Clearing memory contents / Sample printouts



According to the conformity certificate, the instruments fulfill 2004/08/EEC guidelines.

© 1999 Copyright Testo GmbH & Co.

The software and software structure included in the product testo 545 are protected by copyright laws worldwide.

Contents

Instrument configuration
Power save function19
Setting date/time19
Unit selection / Factory reset
Power supply
Error messages
Technical data
Ordering data



Please read prior to measurement

Do not measure on live parts.

Observe storage and transport temperature and max. operating temperature (e.g. protect measuring instrument from direct sunlight)

The V24 cable (PC connection) can be inserted anytime. A simultaneous print command is not possible if the PC cable is connected.

Opening the instrument, inexpert handling and use of force cancels your warranty.



Putting in the batteries

9V block battery is included in delivery.

Open the battery compartment at the back of the instrument. Put in block battery. **Observe polarisation** Close battery compartment.

Refer to "Power supply" Chapter for more information on alternative power supply, charge, battery quality.

The description of the instrument and an overview of the controls provide a quick introduction.




You will receive up to date readings once the instrument is switched on. However, you will still need to update or define the data in the instrument:


- ⇒ Date/Time:
- ⇒ Auto Off:
- ⇒ Units:

Some things can only be set via PC software (See Ordering data):

- ⇒ Location name (8 characters)
- ⇒ Log heading (24 characters), e.g. your company name is printed when the readings are printed.

Keyboard/Connection assignment





- → The symbols on the top line are explained below
- →Name of input socket and parameter
- → Displays reading in line 1
- →Name of location
- →Time/number of points in mean calculation
- → Displays measurement functions

Explanation of symbols:

Counter for the log number in the memory.

When saving manually: number of the measurement saved. M. 00

When saving automatically: number of the measurement series. This counter is needed in order to be able to find single logs or a measurement

series when reading out the memory.

Counter for saving a measurement cycle (required only for automatic N. OOOO saving). The measurement cycle in a measurement series can be found.

Manual saving of a single measurement by pressing the save button

Automatic saving program has been set up. Saving is activated by pressing the button.


Symbol for reading contents of memory on display.

Symbol for deleting memory contents.

If this symbol appears, the printing function is activated. The symbol flashes while data is being transmitted. You can print on the desktop printer by pressing the print button

Shows capacity of battery and rechargeable battery.

If the inner segment no longer appears (symbol flashes), the battery has to be changed or the rechargeable battery has to be recharged. The instrument switches itself off automatically after 1 minute.






























^{*} Multiply displayed value by 10.



Switching on / Saving / Printing




It is possible to activate the following functions during measuring at the touch of a button:

Save readings.

Manual or automatic saving is determined by the save setting (Chapter 5).


Print readings.

Freezing values, maximum readings, minimum readings




Measurement functions

Multi-point mean calculation Mean•




Measurement functions




Return to current measurement.

The location names Location 1 to 99 are specified by the factory.




^{*} Multiply displayed value by 10.

OVERVIEW



Memory settings

Manual / Automatic saving



_{RUTO}→円

_{Ruo}→<mark>円</mark> CYCLE

MIN SEC

Ж

RUTO ► CHIT

MORY

Press the ox button to get to the memory settings mode. Confirm flashing save symbol P via P button

MAN

Manual saving:

Each time is pressed a log of the measurement is saved in the instrument and includes measured values, location, date and time. The counter in the top left corner of the display shows the number of logs saved for this location.

Saving a **log with timed or multi-point mean calculation :** The log includes MIN value, MAX value and mean of the

measurement and also single values in multi-point mean calculations.



ESC

OK

_{Rm}→**凹** CYCLE-N.

OK

OK



Automatic saving:

When this saving function is set, the instrument automatically accepts the measured values at fixed intervals and saves them (=logger operation).

The number of measuring cycles (CYCLE-N.) to be saved and intervals (CYCLE) have to be programmed:

1. Cycle-N.


The instrument automatically offers the maximum possible number of measuring cycles. Set required number using

A / **V** / **b**.

Confirm set value by pressing $\begin{cases} \begin{cases} \begin{cases$

2. Cycle


Automatic saving is started by pressing . The symbol flashes until the programmed measurement series is accepted.




- Cancel saving procedure.
- Starts automatic saving again. An additional measurement series is added.

Memory settings

Reading or printing memory




Clearing memory contents/Sample printouts



Instrument configuration

Power save function / Power supply



The ESC button enables you to change to the current measurement from every menu item.

The ok button has to be kept pressed for approx. 2 seconds when switching on the instrument button).

The blinking position can be changed by pressing or confirmed by pressing or .

Power save function Auto OFF function is switched on ("ON")

If a button has not been pressed in the last 5 minutes or there is no communication with the PC, the instrument switches off automatically.

Exceptions:

- the function is deactivated during timed and multi-point mean calculation
- Automatic saving mode: The function is only activated if saving cycles > 1 min are programmed.
- In the case of an activated function (cycle >1 min) the instrument switches itself on at the measurement time and switches off again. This also occurs if the instrument is switched off via the button after the saving program has been activated.
- BAT: Battery operation with 9 V block battery, Alkali

manganese IEC 6LR61. **AKKU:** Rechargeable battery operation with Testo rechargeable battery (Part no. 0515.0025), Type: Ni-MH IEC 6F22. If the **rechargeable battery** is empty: Recharge battery in external charger (Part no. 0554.0025).

Note:

If the battery/rechargeable battery is removed, the instrument retains set values (date/time) and memory contents for approx. 10 minutes. The data is lost after 10 minutes. The capacity of the battery/rechargeable battery is shown in the display:



25 % (last segment is flashing: the battery/ rechargeable battery is almost empty)

0 % (change battery/recharge rechargeable battery). Instrument switches off after 1 min.

Unit selection / Factory reset / Power supply



Setting date

The flashing position in the display can be set

Setting the time

The blinking position in the display can be set

Lux 🕨 fo

The selected parameter flashes.

➤ Select

OK confirms the selection.

Factory resets all of the settings in the instrument configuration to the factory settings.

- "AUTO OFF" is set at "ON"
- "Lux" is activated

ox confirms the selection and switches to the display of the current measurement.

Error message	Cause	Remedy
Memory full	The memory is full	Clear memory
- -	Measuring range has not been reached	The measured values are outside the allowed measuring range. Switch resolution.
	Connection to the probe has been interrupted.	Please contact a Testo service point.

Technical data

Sensor: Silicon photodiode

Meas. range: 0 to 100,000 Lux

Accuracy: To DIN EN 13032-1

f1 = 6 %

f1 = V (I) adaptation

f2 = 5 %

 $f2 = \cos like rating$

Resolution can 0 to 32,000 Lux 1 Lux be switched: 0 to 100,000 Lux 10 Lux

0 to 3.200 fc 0,1 fc 0 to 10.000 fc 1 fc

Display: 2 line LCD and

2 matrix lines

Battery 9 V IEC 6F22 | 50 h Al-Mn

Battery Automatically check: a Automatically

Operating

temperature: 0 to +50 °C

Storage

temperature: -20 to +70 °C

Dimensions: 220 x 68 x 50 (instrument)

Weight: 500 g (incl. packaging)

Warranty: Instrument: 2 years Probes: 12 months

Tropost 12 months

Ordering data for testo 545	
Measuring instrument and accessories	Part no.
testo 545 incl. probe, batteries and instruction manual and calibration protocol	0560.0545
TopSafe (indestructible protective case) With bench stand and belt clip, protects measuring instrument from impact, dirt	0516.0441
Testo log printer, with 4 AA batteries and 1 roll of thermal paper Prints measured data, location with date and time	0554.0547
ComSoft 3 "Professional" with data management incl. data base, analysis and graphics function, data analysis, trend curve	0554.0830
Transport case For safe storage of measuring instrument, TopSafe, probe and Testo log printer	0516.0445
RS232 cable Connects measuring instrument ↔ PC for data transmission	0409.0178
ISO calibration certificate Calibration point: 1000 Lux	0520.0010

